


Road Erosion Inventory 2016 Town of Springfield, Vermont Last Amended December 2016



- Major road erosion site included in 2016 Road Erosion Report
- 2016 Road Erosion Inventory Priority (Large map only)**
- High
- Medium
- Low
- None
- 2012 Road Erosion Inventory Priority (Small map only)**
- Severe or High
- Low or Culvert Placement Issue



Data Sources:
Road Erosion Inventory (SWCRPC and Town 2016 and 2012), Road centerline (VTrans 2014), Town Boundary (SWCRPC 2013 using Parcels 2013)

VT State Plane, Meters, NAD 83
For planning purposes only
Not for regulatory interpretation
Map Drawn December 7, 2016

